

### **Current Sensors**


# Application Notes of Hall Effect Current and Voltage Sensors

## Some current sensors require a 2 terminal power supply.

Spec Example 1:

Supply Voltage:	V <sub>cc</sub> = +12V, +15V, +24V±15%
Current Consumption:	<i>I</i> <sub>c</sub> <20mA
Isolation Voltage:	2.5kV, 50/60Hz, 1 min.

#### Connection



### Other current sensors may require a 3 terminal power supply.

Spec Example 2:

Supply Voltage:	V <sub>cc</sub> = ±12V ~ ±15V ±15%
Current Consumption:	<i>I</i> <sub>c</sub> <25mA
Isolation Voltage:	2.5kV, 50/60Hz, 1 min.

#### Connection

